

**FISHER**

143-0-4204-00300  
143-0-4204-00400  
Sears: 46-391261-3  
PRB Replacement Tire = ST.985


P/N:  
VA01



**FISHER**

143-0-4204-00100  
Hitachi: 6413684  
RCA: 148193  
PRB Replacement Tire = ST1.243

P/N:  
VA02



**FISHER**

143-0-4804-00100  
PRB Replacement Tire = ST.390


P/N:  
VA03



**FISHER**

143-0-4904-00900

P/N:  
VA04



**AKAI**

MI-361964  
BL-B353110  
No PRB Replacement Tire

P/N:  
VA054



**AKAI**

MZ-366960  
**Includes VA056**  
PRB Replacement Tire = ST1.118


P/N:  
VA055



**FISHER/SANYO**

143-0-741T-20001  
**Part of VA05, VA06,  
VA101, VA103**  
PRB Replacement Tire = ST.685


P/N:  
VA07



**FISHER**

143-0-4204-00700  
PRB Replacement Tire = ST1.130


P/N:  
VA08



**FISHER**

143-0-4904-02400

P/N:  
VA09



**JVC**

PU48967B  
Dual, Kenwood, Sansui:  
PU48967B  
PRB Replacement Tire = ST1.113

P/N:  
VA10



**JVC**

PU51380A-2  
PRB Replacement Tire = ST.463


P/N:  
VA11



**JVC**

PU51402A  
NEC: 79V20041  
Penney, JC: PU51402A  
PRB Replacement Tire = ST.689

P/N:  
VA12



**JVC**

PU55373  
NEC: 79V23059  
PRB Replacement Tire = ST.463


P/N:  
VA13



**JVC**

PU56043-1-4  
NEC: 79V29402  
Toshiba: 70316131  
Zenith: 861-654-01  
**Part of VA752 & VA756**  
PRB Replacement Tire = ST.948


P/N:  
VA14



**JVC**

PU56044-1-4  
NEC: 79V29402  
Toshiba: 70316131  
Zenith: 861-655-01  
**Part of VA752 & VA756**  
PRB Replacement Tire = ST.948

P/N:  
VA15



**JVC**

PU55374/3/8  
NEC: 79V24802  
PRB Replacement Tire = ST.988

P/N:  
VA18



### PANASONIC

VXP0329  
Magnavox, Philco, Sylvania:  
VXP0329  
RCA: 152674  
PRB Replacement Tire = ST1.330

P/N:  
VA20



### PANASONIC

VXP0401  
RCA: 155574  
PRB Replacement Tire = ST1.243


P/N:  
VA21



### PANASONIC

VXP0521, VXPS0069  
Gen. Elect.: EW2X953  
**Part of VA500  
& Includes VA27**  
PRB Replacement Tire = ST1.165

P/N:  
VA22



### PANASONIC

VXP0174, VXP0245  
NAP: 7044250160  
Philco: 07-28777-445/447  
Quasar: VXP0174  
RCA: 144263  
Sylvania: 07-28777-447  
PRB Replacement Tire = ST1.160

P/N:  
VA23



### PANASONIC

VXP0331  
Gen. Elect.: EW2X762  
Magnavox, Philco, Sylvania:  
VXP0331  
NAP: 7044250019  
RCA: 152683  
PRB Replacement Tire = ST1.230

P/N:  
VA25



### PANASONIC

VXP0344  
Magnavox, Quasar, Sylvania:  
VXP0344  
NAP: 7044250414  
Philco: 07-28977-415  
RCA: 148580  
PRB Replacement Tire = ST1.330

P/N:  
VA26



### PANASONIC

VXPS0116  
Gen. Elect.: EW2X0953  
**Part of VA22, VA500**  
PRB Replacement Tire = ST1.165

P/N:  
VA27



### PANASONIC

VXPS0054  
Gen. Elect.: EW2X752  
Magnavox, Philco, Sylvania:  
VXPS0054  
NAP: 7044250337  
RCA: 155739  
PRB Replacement Tire = ST1.370

P/N:  
VA28



### TOSHIBA

70326538,  
70326575, 70326616  
RCA: 162662  
PRB Replacement Tire = ST1.211

P/N:  
VA30



### RCA/HITACHI

Gen. Elect.: EW2X335  
Hitachi: 6825371, 6865575,  
6875371, 6875372, 6886971  
RCA: 164113  
**Use With PRB# VA49**  
PRB Replacement Tire = ST1.014

P/N:  
VA40



### RCA/HITACHI

Gen. Elect.: EW2X0305,  
EW2X0511  
Hitachi: 6861471  
RCA: 150614  
PRB Replacement Tire = ST1.113

P/N:  
VA41



### RCA/HITACHI

Gen. Elect.: EW2X0512  
Hitachi: 6861481, 6861482  
RCA: 150650  
PRB Replacement Tire = ST.670

P/N:  
VA42



### RCA/HITACHI

Hitachi: 6875386, 6875387,  
6876043, 6876045  
RCA: 158190  
PRB Replacement Tire = ST1.165

P/N:  
VA44




### RCA/HITACHI

Hitachi: 6886792  
RCA: 177194, 194883  
When replacing the clutch plate,  
#180935 or the idler assembly,  
#180931 in a P-line VCR, BOTH  
the clutch and idler must be  
changed to the M-line type to  
maintain compatibility.

**Use With PRB# VA47**

P/N:  
VA45



### RCA/HITACHI

Hitachi: 6413663  
RCA: 147060

P/N:  
VA46



## RCA/HITACHI

RCA: 177206

Hitachi: 6886824

When replacing the clutch plate, #180935 or the idler assembly, #180931 in a P-line VCR, BOTH the clutch and idler must be changed to the M-line type to maintain compatibility.

**Use With PRB# VA45**

PRB Replacement Belt = SCQ5.3

P/N:  
VA47



## RCA/HITACHI

Pulley for 6886824  
**Part of VA47**

P/N:  
VA48




## RCA/HITACHI

Hitachi: 6879515,  
7375446

**Use With PRB# VA40**

PRB Replacement Belt = SCQ5.3

P/N:  
VA49



## SAMSUNG

Part of 5224-704-2208V

**Part of VA53**

PRB Replacement Tire = ST1.218

P/N:  
VA50



## GOLDSTAR

431-014A

PRB Replacement Tire = ST1.396

P/N:  
VA51



## GOLDSTAR

431-017A

PRB Replacement Tire = ST1.218

P/N:  
VA52



## SAMSUNG


5224-704-2208

9000-250-3308V

**Includes VA50**

PRB Replacement Tire = ST1.218

P/N:  
VA53



## SAMSUNG

6052-600-3101/V

6052-611-310/V

Gen. Elect., RCA:192242

Penney, JC:66052-600-310

Toshiba: BZ730066

PRB Replacement Tire = ST1.152

P/N:  
VA54



## SAMSUNG

5253-701-1105V

PRB Replacement Tire = ST.977

P/N:  
VA55



## SAMSUNG

5153-600-0114V,

65153-600-011

Gen. Elect.: 186480

RCA: 186480, 187878

**Includes VA57**

PRB Replacement Tire = ST1.152

P/N:  
VA56



## SAMSUNG

Part of 5153-600-0114V,

65153-600-011

**Part of VA56**

PRB Replacement Tire = ST1.152

P/N:  
VA57



## SHARP

NIDL0005GEZZ

PRB Replacement Tire = ST1.350

P/N:  
VA60




## SHARP

NIDL0006GEZZ

PRB Replacement Tire = ST1.211

P/N:  
VA61




## SHARP

NPLYV0107GEZZ

NPLYV0111GEZZ

PRB Replacement Tire = ST1.016

P/N:  
VA63



## SHARP

NPLYV0103GEZZ

PRB Replacement Tire = ST1.016

P/N:  
VA67




## SONY

X-3653-315-0

X-3653-315-3

PRB Replacement Tire = ST.925


P/N:  
VA70



**NEC/LLOYDS**

NEC: 16178179 (clutch),  
16178176, 16180801,  
16185251  
Lloyds: 016118-0801  
PRB Replacement Tire = ST1.205


P/N:  
VA80



**MITSUBISHI**

522P002010  
Also used in Emerson VCRs  
PRB Replacement Tire = ST.599


P/N:  
VA90



**MITSUBISHI**

522A00201  
PRB Replacement Tire = ST1.014


P/N:  
VA91



**MITSUBISHI**

641B093010

P/N:  
VA92



**MITSUBISHI**

641B094010

P/N:  
VA93



**MITSUBISHI**

641D710010


P/N:  
VA94



**MITSUBISHI**

641D711010


P/N:  
VA95



**MITSUBISHI**

522B017010  
PRB Replacement Tire = ST.850

P/N:  
VA96



**MITSUBISHI**

522B01801


P/N:  
VA97



**MITSUBISHI**

522B02002


P/N:  
VA98



**FISHER/SANYO**

Fisher: 143-0-662T-15620,  
143-0-662T-1560  
Sanyo: 613-037-4899  
PRB Replacement Tire = ST1.118


P/N:  
VA100



**FISHER/SANYO**

143-0-662T-10350  
*Includes VA07*  
PRB Replacement Tire = ST.685 (2)


P/N:  
VA103



**FISHER/SANYO**

143-0-662T-15621  
PRB Replacement Tire = ST1.118

P/N:  
VA104



**FISHER/SANYO**

Fisher: 143-0-662T-14730  
Sanyo: 613-037-4875  
PRB Replacement Tire = ST1.208

P/N:  
VA105



**JVC**

PU58645-1-1/3/4  
Zenith: 948-520,  
948-522  
PRB Replacement Tire = ST1.130

P/N:  
VA150



**PANASONIC**

VXP0213  
Magnavox: 70C002-4  
NAP: 7044250156  
Philco, Sylvania: 07-28777-442  
Quasar: 49-90369A18  
RCA: 144265  
PRB Replacement Tire = ST.752

P/N:  
VA200



**PANASONIC**

VXP0463  
VXP0515

P/N:  
VA202



**PANASONIC**

VXP0343, VXLS0081  
PRB Replacement Tire = ST.470

P/N:  
VA204



**PANASONIC**

VXL0997

P/N:  
VA207



**PANASONIC**

Sector Gear  
VDG0351  
VDGS0200

P/N:  
VA210



**PANASONIC**

VXP0599  
Part Of VA500  
PRB Replacement Tire = ST.753

P/N:  
VA212



**PANASONIC**

VXP0595


P/N:  
VA213



**PANASONIC**

VXLS0383  
VXLS0454

P/N:  
VA215



**PANASONIC**

VXP0523

P/N:  
VA217



**FUNAI**

8000-12-304

P/N:  
VA350



**DAEWOO**

97SA507200  
PRB Replacement Tire = ST1.156

P/N:  
VA450



**DAEWOO**

97SA387600  
PRB Replacement Tire = ST.675

P/N:  
VA451



**DAEWOO**

No PRB Replacement Tire


P/N:  
VA452



**GOLDSTAR**

321-149B  
Includes VA22, VA27,  
VA212, VA506  
PRB Replacement Tire = ST1.165  
& ST.753


P/N:  
VA500



**EMERSON**

850A200004

P/N:  
VA501



**GOLDSTAR**

321-218A  
Emerson: 321-218A  
Zenith: 861-707


P/N:  
VA502



**GOLDSTAR**

321-526A  
Includes VA504, VA506


P/N:  
VA503



**GOLDSTAR**

386-139A  
321-253A  
Part Of VA503


P/N:  
VA504



**GOLDSTAR**

435-038A


P/N:  
VA505



**GOLDSTAR**

321-256A  
Part Of VA500, VA503

P/N:  
VA506



**EMERSON**

850A200005


P/N:  
VA551



**EMERSON**

850A20021


P/N:  
VA552



**EMERSON**

850A20020

P/N:  
VA553



**EMERSON**

VCR Post Limiter  
850-A-600-039


P/N:  
VA554



**JVC**

PU57658 B-3/B-4  
*Includes VA14 & VA15*  
PRB Replacement Tire = ST.948 (2)  
*(VA752 has 2 posts)*

P/N:  
VA752



**MITSUBISHI**

641C63601

P/N:  
VA753



**MITSUBISHI**

641C52501

P/N:  
VA754



**FUNAI**

8000-12-305


P/N:  
VA755



**JVC**

PU55822 A-4/A-8  
*Includes VA14 & VA15*  
PRB Replacement Tire = ST.948 (2)  
*(VA756 has 1 post)*

P/N:  
VA756



**FUNAI**

62D805909302


P/N:  
VA757



**HITACHI**

6897094  
6897095

P/N:  
VA758



**FISHER/SANYO**

613-077-3586  
*Use With PRB# VA761*

P/N:  
VA759



**SAMSUNG**

66054-609-410,  
6054-609-4107V  
Thomson: 201989


P/N:  
VA760



**FISHER/SANYO**

613-022-2534  
*Use With PRB# VA759*

P/N:  
VA761



**GOLDSTAR**

433-015A

P/N:  
VA762



**SAMSUNG**

6053-604-4114V,  
66053-604-410,  
Thomson: 207493,  
201040, 210841  
No PRB Replacement Tire


P/N:  
VA763



**GOLDSTAR**

321-397D  
Zenith: 812-2029-02

P/N:  
VA764



**ORIGINAL**

**GOLDSTAR**

333-201B

P/N:  
VA765



**ORIGINAL**

**GOLDSTAR**

333-208A  
Zenith: 917-863

P/N:  
VA766



**ORIGINAL**

**GOLDSTAR**

374-003A

P/N:  
VA767



**ORIGINAL**

**GOLDSTAR**  
374-005A  
Zenith: 928-129

P/N:  
VA768



**ORIGINAL**

**GOLDSTAR**  
386-387B

P/N:  
VA769



**ORIGINAL**

**GOLDSTAR**  
433-007A

P/N:  
VA770



**ORIGINAL**

**GOLDSTAR**  
435-132A

P/N:  
VA771



**ORIGINAL**

**GOLDSTAR**  
435-257B

P/N:  
VA772



**ORIGINAL**

**GOLDSTAR**  
435-450A

P/N:  
VA773



**ORIGINAL**

**JVC**  
PQ30028  
Zenith: 834-163

P/N:  
VA774



**ORIGINAL**

**JVC**  
PQ40068  
Zenith: 834-160


P/N:  
VA775



**ORIGINAL**

**JVC**  
PQ40066-1-2  
Zenith: 834-164-01

P/N:  
VA776



**ORIGINAL**

**JVC**  
PQ40067-1-2  
Zenith: 834-165-01

P/N:  
VA777



**ORIGINAL**

**JVC**  
PTU96031-678C

P/N:  
VA778



**ORIGINAL**

**SONY**  
X-3727-782-1

P/N:  
VA779



**ORIGINAL**

**SONY**  
X-2625-356-2


P/N:  
VA781



**ORIGINAL**

**SONY**  
3-736-116-01

P/N:  
VA782



**ORIGINAL**

**SONY**  
3-736-143-01

P/N:  
VA783



**ORIGINAL**

**SONY**  
3-736-176-01

P/N:  
VA784



**ORIGINAL**

**JVC**  
PQ43567A-13

P/N:  
VA785



**ORIGINAL**

## Audio Idler Assembly

**SONY**  
X-4920-346-1  
PRB Replacement Tire=ST.525

P/N: AUD01



**ORIGINAL**