

FISHER

143-0-4204-00300
143-0-4204-00400
Sears: 46-391261-3
PRB Replacement Tire = ST.985


P/N:
VA01



FISHER

143-0-4204-00100
Hitachi: 6413684
RCA: 148193
PRB Replacement Tire = ST1.243

P/N:
VA02



FISHER

143-0-4804-00100
PRB Replacement Tire = ST.390


P/N:
VA03



FISHER

143-0-4904-00900

P/N:
VA04



AKAI

MI-361964
BL-B353110
No PRB Replacement Tire

P/N:
VA054



AKAI

MZ-366960
Includes VA056
PRB Replacement Tire = ST1.118


P/N:
VA055



FISHER/SANYO

143-0-741T-20001
**Part of VA05, VA06,
VA101, VA103**
PRB Replacement Tire = ST.685


P/N:
VA07



FISHER

143-0-4204-00700
PRB Replacement Tire = ST1.130


P/N:
VA08



FISHER

143-0-4904-02400

P/N:
VA09



JVC

PU48967B
Dual, Kenwood, Sansui:
PU48967B
PRB Replacement Tire = ST1.113

P/N:
VA10



JVC

PU51380A-2
PRB Replacement Tire = ST.463

P/N:
VA11



JVC

PU51402A
NEC: 79V20041
Penney, JC: PU51402A
PRB Replacement Tire = ST.689

P/N:
VA12



JVC

PU55373
NEC: 79V23059
PRB Replacement Tire = ST.463


P/N:
VA13



JVC

PU56043-1-4
NEC: 79V29402
Toshiba: 70316131
Zenith: 861-654-01
Part of VA752 & VA756
PRB Replacement Tire = ST.948


P/N:
VA14



JVC

PU56044-1-4
NEC: 79V29402
Toshiba: 70316131
Zenith: 861-655-01
Part of VA752 & VA756
PRB Replacement Tire = ST.948

P/N:
VA15



JVC

PU55374/3/8
NEC: 79V24802
PRB Replacement Tire = ST.988

P/N:
VA18



PANASONIC

VXP0329
Magnavox, Philco, Sylvania:
VXP0329
RCA: 152674
PRB Replacement Tire = ST1.330

P/N:
VA20



PANASONIC

VXP0401
RCA: 155574
PRB Replacement Tire = ST1.243


P/N:
VA21



PANASONIC

VXP0521, VXPS0069
Gen. Elect.: EW2X953
**Part of VA500
& Includes VA27**
PRB Replacement Tire = ST1.165

P/N:
VA22



PANASONIC

VXP0174, VXP0245
NAP: 7044250160
Philco: 07-28777-445/447
Quasar: VXP0174
RCA: 144263
Sylvania: 07-28777-447
PRB Replacement Tire = ST1.160

P/N:
VA23



PANASONIC

VXP0331
Gen. Elect.: EW2X762
Magnavox, Philco, Sylvania:
VXP0331
NAP: 7044250019
RCA: 152683
PRB Replacement Tire = ST1.230

P/N:
VA25



PANASONIC

VXP0344
Magnavox, Quasar, Sylvania:
VXP0344
NAP: 7044250414
Philco: 07-28977-415
RCA: 148580
PRB Replacement Tire = ST1.330

P/N:
VA26



PANASONIC

VXPS0116
Gen. Elect.: EW2X0953
Part of VA22, VA500
PRB Replacement Tire = ST1.165

P/N:
VA27



PANASONIC

VXPS0054
Gen. Elect.: EW2X752
Magnavox, Philco, Sylvania:
VXPS0054
NAP: 7044250337
RCA: 155739
PRB Replacement Tire = ST1.370

P/N:
VA28



TOSHIBA

70326538,
70326575, 70326616
RCA: 162662
PRB Replacement Tire = ST1.211

P/N:
VA30



RCA/HITACHI

Gen. Elect.: EW2X335
Hitachi: 6825371, 6865575,
6875371, 6875372, 6886971
RCA: 164113
Use With PRB# VA49
PRB Replacement Tire = ST1.014

P/N:
VA40



RCA/HITACHI

Gen. Elect.: EW2X0305,
EW2X0511
Hitachi: 6861471
RCA: 150614
PRB Replacement Tire = ST1.113


P/N:
VA41



RCA/HITACHI

Gen. Elect.: EW2X0512
Hitachi: 6861481, 6861482
RCA: 150650
PRB Replacement Tire = ST.670

P/N:
VA42



RCA/HITACHI

Hitachi: 6875386, 6875387,
6876043, 6876045
RCA: 158190
PRB Replacement Tire = ST1.165


P/N:
VA44



RCA/HITACHI

Hitachi: 6886792
RCA: 177194, 194883
When replacing the clutch plate,
#180935 or the idler assembly,
#180931 in a P-line VCR, BOTH
the clutch and idler must be
changed to the M-line type to
maintain compatibility.
Use With PRB# VA47

P/N:
VA45



RCA/HITACHI

Hitachi: 6413663
RCA: 147060

P/N:
VA46



RCA/HITACHI

RCA: 177206

Hitachi: 6886824

When replacing the clutch plate, #180935 or the idler assembly, #180931 in a P-line VCR, BOTH the clutch and idler must be changed to the M-line type to maintain compatibility.

Use With PRB# VA45

PRB Replacement Belt = SCQ5.3

P/N:
VA47



RCA/HITACHI

Pulley for 6886824
Part of VA47

P/N:
VA48




RCA/HITACHI

Hitachi: 6879515,
7375446

Use With PRB# VA40

PRB Replacement Belt = SCQ5.3

P/N:
VA49



SAMSUNG

Part of 5224-704-2208V

Part of VA53

PRB Replacement Tire = ST1.218

P/N:
VA50



GOLDSTAR

431-014A

PRB Replacement Tire = ST1.396

P/N:
VA51



GOLDSTAR

431-017A

PRB Replacement Tire = ST1.218

P/N:
VA52



SAMSUNG


5224-704-2208

9000-250-3308V

Includes VA50

PRB Replacement Tire = ST1.218

P/N:
VA53



SAMSUNG

6052-600-3101/V

6052-611-310/V

Gen. Elect., RCA:192242

Penney, JC:66052-600-310

Toshiba: BZ730066

PRB Replacement Tire = ST1.152

P/N:
VA54



SAMSUNG

5253-701-1105V

PRB Replacement Tire = ST.977

P/N:
VA55



SAMSUNG

5153-600-0114V,

65153-600-011


Gen. Elect.: 186480

RCA: 186480, 187878

Includes VA57

PRB Replacement Tire = ST1.152

P/N:
VA56



SAMSUNG

Part of 5153-600-0114V,

65153-600-011

Part of VA56

PRB Replacement Tire = ST1.152

P/N:
VA57



SHARP

NIDL0005GEZZ

PRB Replacement Tire = ST1.350

P/N:
VA60




SHARP

NIDL0006GEZZ

PRB Replacement Tire = ST1.211

P/N:
VA61




SHARP

NPLYV0107GEZZ

NPLYV0111GEZZ

PRB Replacement Tire = ST1.016

P/N:
VA63



SHARP

NPLYV0103GEZZ

PRB Replacement Tire = ST1.016

P/N:
VA67



SONY

X-3653-315-0

X-3653-315-3

PRB Replacement Tire = ST.925


P/N:
VA70



NEC/LLOYDS

NEC: 16178179 (clutch),
16178176, 16180801,
16185251
Lloyds: 016118-0801
PRB Replacement Tire = ST1.205


P/N:
VA80



MITSUBISHI

522P002010
Also used in Emerson VCRs
PRB Replacement Tire = ST.599


P/N:
VA90



MITSUBISHI

522A00201
PRB Replacement Tire = ST1.014


P/N:
VA91



MITSUBISHI

641B093010

P/N:
VA92



MITSUBISHI

641B094010

P/N:
VA93



MITSUBISHI

641D710010


P/N:
VA94



MITSUBISHI

641D711010


P/N:
VA95



MITSUBISHI

522B017010
PRB Replacement Tire = ST.850

P/N:
VA96



MITSUBISHI

522B01801

P/N:
VA97



MITSUBISHI

522B02002


P/N:
VA98



FISHER/SANYO

Fisher: 143-0-662T-15620,
143-0-662T-1560
Sanyo: 613-037-4899
PRB Replacement Tire = ST1.118


P/N:
VA100



FISHER/SANYO

143-0-662T-10350
Includes VA07
PRB Replacement Tire = ST.685 (2)


P/N:
VA103



FISHER/SANYO

143-0-662T-15621
PRB Replacement Tire = ST1.118

P/N:
VA104



FISHER/SANYO

Fisher: 143-0-662T-14730
Sanyo: 613-037-4875
PRB Replacement Tire = ST1.208

P/N:
VA105



JVC

PU58645-1-1/3/4
Zenith: 948-520,
948-522
PRB Replacement Tire = ST1.130

P/N:
VA150



PANASONIC

VXP0213
Magnavox: 70C002-4
NAP: 7044250156
Philco, Sylvania: 07-28777-442
Quasar: 49-90369A18
RCA: 144265
PRB Replacement Tire = ST.752

P/N:
VA200



PANASONIC

VXP0463
VXP0515


P/N:
VA202



PANASONIC

VXP0343, VXLS0081
PRB Replacement Tire = ST.470

P/N:
VA204



PANASONIC

VXL0997

P/N:
VA207



PANASONIC

Sector Gear
VDG0351
VDGS0200

P/N:
VA210



PANASONIC

VXP0599
Part Of VA500
PRB Replacement Tire = ST.753

P/N:
VA212



PANASONIC

VXP0595


P/N:
VA213



PANASONIC

VXLS0383
VXLS0454

P/N:
VA215



PANASONIC

VXP0523

P/N:
VA217



FUNAI

8000-12-304

P/N:
VA350



DAEWOO

97SA507200
PRB Replacement Tire = ST1.156

P/N:
VA450



DAEWOO

97SA387600
PRB Replacement Tire = ST.675

P/N:
VA451



DAEWOO

No PRB Replacement Tire


P/N:
VA452



GOLDSTAR

321-149B
Includes VA22, VA27,
VA212, VA506
PRB Replacement Tire = ST1.165
& ST.753


P/N:
VA500



EMERSON

850A200004

P/N:
VA501



GOLDSTAR

321-218A
Emerson: 321-218A
Zenith: 861-707


P/N:
VA502



GOLDSTAR

321-526A
Includes VA504, VA506


P/N:
VA503



GOLDSTAR

386-139A
321-253A
Part Of VA503


P/N:
VA504



GOLDSTAR

435-038A


P/N:
VA505



GOLDSTAR

321-256A
Part Of VA500, VA503

P/N:
VA506



EMERSON

850A200005


P/N:
VA551



EMERSON

850A20021


P/N:
VA552



EMERSON

850A20020

P/N:
VA553



EMERSON

VCR Post Limiter
850-A-600-039


P/N:
VA554



JVC

PU57658 B-3/B-4
Includes VA14 & VA15
PRB Replacement Tire = ST.948 (2)
(VA752 has 2 posts)

P/N:
VA752



MITSUBISHI

641C63601

P/N:
VA753



MITSUBISHI

641C52501

P/N:
VA754



FUNAI

8000-12-305


P/N:
VA755



JVC

PU55822 A-4/A-8
Includes VA14 & VA15
PRB Replacement Tire = ST.948 (2)
(VA756 has 1 post)

P/N:
VA756



FUNAI

62D805909302


P/N:
VA757



HITACHI

6897094
6897095

P/N:
VA758



FISHER/SANYO

613-077-3586
Use With PRB# VA761


P/N:
VA759



SAMSUNG

66054-609-410,
6054-609-4107V
Thomson: 201989

P/N:
VA760



FISHER/SANYO

613-022-2534
Use With PRB# VA759

P/N:
VA761



GOLDSTAR

433-015A

P/N:
VA762



SAMSUNG

6053-604-4114V,
66053-604-410,
Thomson: 207493,
201040, 210841
No PRB Replacement Tire


P/N:
VA763



GOLDSTAR

321-397D
Zenith: 812-2029-02

P/N:
VA764



ORIGINAL

GOLDSTAR

333-201B

P/N:
VA765



ORIGINAL

GOLDSTAR

333-208A
Zenith: 917-863

P/N:
VA766



ORIGINAL

GOLDSTAR

374-003A

P/N:
VA767



ORIGINAL

GOLDSTAR
374-005A
Zenith: 928-129

P/N:
VA768



ORIGINAL

GOLDSTAR
386-387B

P/N:
VA769



ORIGINAL

GOLDSTAR
433-007A

P/N:
VA770



ORIGINAL

GOLDSTAR
435-132A

P/N:
VA771



ORIGINAL

GOLDSTAR
435-257B

P/N:
VA772



ORIGINAL

GOLDSTAR
435-450A

P/N:
VA773



ORIGINAL

JVC
PQ30028
Zenith: 834-163

P/N:
VA774



ORIGINAL

JVC
PQ40068
Zenith: 834-160


P/N:
VA775



ORIGINAL

JVC
PQ40066-1-2
Zenith: 834-164-01

P/N:
VA776



ORIGINAL

JVC
PQ40067-1-2
Zenith: 834-165-01

P/N:
VA777



ORIGINAL

JVC
PTU96031-678C

P/N:
VA778



ORIGINAL

SONY
X-3727-782-1

P/N:
VA779



ORIGINAL

SONY
X-2625-356-2


P/N:
VA781



ORIGINAL

SONY
3-736-116-01

P/N:
VA782



ORIGINAL

SONY
3-736-143-01

P/N:
VA783



ORIGINAL

SONY
3-736-176-01

P/N:
VA784



ORIGINAL

JVC
PQ43567A-13

P/N:
VA785



ORIGINAL

Audio Idler Assembly

SONY
X-4920-346-1
PRB Replacement Tire=ST.525

P/N: AUD01



ORIGINAL